

Secret

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER



25X1

Imagery analysis report

**FENCER A Maintenance And Repair Depot
Siauliai, USSR (S)**

Secret

WNINTEL

Z-20018/80

IAR-0102/80

JUNE 1980

Copy 167

Warning Notice
Intelligence Sources and Methods Involved
(WNINTEL) or (D)

NATIONAL SECURITY INFORMATION
Unauthorized Disclosure Subject to Criminal Sanctions



25X1

DISSEMINATION CONTROL ABBREVIATIONS

NOFORN-	Not Releasable to Foreign Nationals
NOCONTRACT-	Not Releasable to Contractors or Contractor/Consultants
PROPIN-	Caution-Proprietary Information Involved
USIBONLY-	USIB Departments Only
ORCON-	Dissemination and Extraction of Information Controlled by Originator
REL . . .	This Information has been Authorized for Release to . . .

SECRET

25X1

FENCER A MAINTENANCE AND REPAIR DEPOT, SIAULIAI, USSR (S)

1. (S/D) The first maintenance and repair depot for the FENCER A fighter/bomber was identified at Siauliai Repair Base [] USSR (Figure 1), [] This repair depot, which also supports FITTER A maintenance and repair, is collocated with Siauliai Airfield [] a jointly occupied airfield which supports a FLOGGER counterair regiment, an air defense unit of MOSS aircraft, and a CUB military transport regiment.

25X1

25X1


25X1

25X1

2. (S/D) [] four FENCER A were observed at the repair depot (Figure 2). This was the first observation of more than two FENCER A here [] when FENCER A were initially identified. Two palletized FITTER and numerous pallets were also observed [] Palletized FITTER are not usually seen here. The presence of the FENCER A, in conjunction with a decline in the number of FITTER observed since 1979 and the construction of a new maintenance building, indicates a trend toward an increase in FENCER A repair and overhaul at the depot.

25X1

25X1

**FIGURE 1. LOCATION OF SIAULIAI AIRFIELD AND REPAIR BASE, USSR****SECRET**

Page Denied

Secret

Secret